



Transportation Pooled Fund Program



Report No. 405160-13-1
Report Date: August 2009

**DEVELOPMENT AND TESTING OF A CONCRETE
BARRIER DESIGN FOR USE IN FRONT OF SLOPE OR
ON MSE WALL**

by

Nauman M. Sheikh
Associate Transportation Researcher

Roger P. Bligh, P.E.
Research Engineer

and

Wanda L. Menges
Research Specialist

Contract No.: T4541
Test No.: 405160-13-1
Test Date: 2009-04-16

Sponsored by
**Roadside Safety Research Program Pooled Fund
Study No. TPF-5(114)**

TEXAS TRANSPORTATION INSTITUTE PROVING GROUND

Mailing Address:
Roadside Safety & Physical Security
Texas A&M University System
3135 TAMU
College Station, TX 77843-3135


Located at:
Texas A&M Riverside Campus
Building 7091
3100 State Highway 47
Bryan, TX 77807




DISCLAIMER

The contents of this report reflect the views of the authors who are solely responsible for the facts and accuracy of the data, and the opinions, findings and conclusions presented herein. The contents do not necessarily reflect the official views or policies of the Washington State Department of Transportation, the Roadside Pooled Fund Program, The Texas A&M University System, or Texas Transportation Institute. This report does not constitute a standard, specification, or regulation. In addition, the above listed agencies assume no liability for its contents or use thereof. The names of specific products or manufacturers listed herein do not imply endorsement of those products or manufacturers. The results reported herein apply only to the article being tested.

The bogie testing and the full-scale crash test reported herein were performed at Texas Transportation Institute (TTI) Proving Ground. TTI Proving Ground is an International Standards Organization (ISO) 17025 accredited laboratory with American Association for Laboratory Accreditation (A2LA) Mechanical Testing certificate 2821.01. The bogie testing and the full-scale crash test were performed according to TTI Proving Ground quality procedures and according to the *MASH08* guidelines and standards, herein referred to as MASH.^(3,4)



Wanda L. Menges, Research Specialist
Deputy Quality Manager



Richard A. Zimmer, Senior Research Specialist
Test Facility Manager
Quality Manager
Technical Manager

1. Report No.	2. Government Accession No.	3. Recipient's Catalog No.	
4. Title and Subtitle DEVELOPMENT AND TESTING OF A CONCRETE BARRIER DESIGN FOR USE IN FRONT OF SLOPE OR ON MSE WALL		5. Report Date August 2009	6. Performing Organization Code
7. Author(s) Nauman M. Sheikh, Roger P. Bligh, and Wanda L. Menges		8. Performing Organization Report No. 405160-13-1	
9. Performing Organization Name and Address Texas Transportation Institute Proving Ground The Texas A&M University System College Station, Texas 77843-3135		10. Work Unit No. (TRAIS)	11. Contract or Grant No. T4541
12. Sponsoring Agency Name and Address Washington State Department of Transportation Transportation Building, MS 47372 Olympia, Washington 98504-7372		13. Type of Report and Period Covered Test Report March 2008 – August 2009	
		14. Sponsoring Agency Code	
15. Supplementary Notes Research Study Title: Task Order #13 – Concrete Barrier Design for Use in Front of a Slope or on MSE Wall Name of Contacting Representative: Dave Olson			
16. Abstract <p>The objective of this research was to restrict lateral deflection of a concrete barrier when placed adjacent to steep slopes or on top of Mechanically Stabilized Earth (MSE) walls, without using a concrete moment slab. The final design was required to incorporate 20-ft long single slope barrier segments with grouted rebar grid connection. The researchers first evaluated the performance of the free-standing barrier with grouted rebar-grid connection using a smaller scale bogie impact test and simulation analysis. It was determined that the grouted rebar-grid connection did not provide enough strength to restrict lateral deflections.</p> <p>The researchers then evaluated restricting the deflection of the barrier by embedding it 10 inches in soil. The barrier was placed in front of a 1.5H:1V slope. The offset of the barrier from the slope break point was restricted to 2 ft. Another phase of bogie testing and simulation analysis was performed to evaluate the performance of the grouted rebar grid connection in the embedded configuration. Results of the simulation analysis showed that the embedded barrier system will result in acceptably reduced lateral deflections.</p> <p>A 100-ft long installation of the embedded single-slope barrier in front of a 1.5H:1V slope was subsequently crash tested under <i>Manual for Assessing Safety Hardware (MASH)</i> criteria. The design performed acceptably according to the requirements of <i>MASH</i> and the maximum static barrier deflection was 5.5 inches. While the barrier was tested in front of a 1.5H:1V slope, due to a relatively small lateral deflection, it is also recommended for use on top of MSE walls as long as a minimum 2-ft lateral offset is maintained between the back of the barrier and the wall.</p>			
17. Key Words Concrete barrier, embedded barrier, restrained barrier, slope, MSE wall, soil, single slope barrier, rebar grid		18. Distribution Statement Copyrighted. Not to be copied or reprinted without consent from Washington DOT.	
19. Security Classif.(of this report) Unclassified	20. Security Classif.(of this page) Unclassified	21. No. of Pages 80	22. Price

SI* (MODERN METRIC) CONVERSION FACTORS

APPROXIMATE CONVERSIONS TO SI UNITS

Symbol	When You Know	Multiply By	To Find	Symbol
LENGTH				
in	inches	25.4	millimeters	mm
ft	feet	0.305	meters	m
yd	yards	0.914	meters	m
mi	miles	1.61	kilometers	km
AREA				
in ²	square inches	645.2	square millimeters	mm ²
ft ²	square feet	0.093	square meters	m ²
yd ²	square yard	0.836	square meters	m ²
ac	acres	0.405	hectares	ha
mi ²	square miles	2.59	square kilometers	km ²
VOLUME				
fl oz	fluid ounces	29.57	milliliters	mL
gal	gallons	3.785	liters	L
ft ³	cubic feet	0.028	cubic meters	m ³
yd ³	cubic yards	0.765	cubic meters	m ³
NOTE: volumes greater than 1000 L shall be shown in m ³				
MASS				
oz	ounces	28.35	grams	g
lb	pounds	0.454	kilograms	kg
T	short tons (2000 lb)	0.907	megagrams (or "metric ton")	Mg (or "t")
TEMPERATURE (exact degrees)				
°F	Fahrenheit	5 (F-32)/9 or (F-32)/1.8	Celsius	°C
ILLUMINATION				
fc	foot-candles	10.76	lux	lx
fl	foot-Lamberts	3.426	candela/m ²	cd/m ²
FORCE and PRESSURE or STRESS				
lbf	poundforce	4.45	newtons	N
lbf/in ²	poundforce per square inch	6.89	kilopascals	kPa

APPROXIMATE CONVERSIONS FROM SI UNITS

Symbol	When You Know	Multiply By	To Find	Symbol
LENGTH				
mm	millimeters	0.039	inches	in
m	meters	3.28	feet	ft
m	meters	1.09	yards	yd
km	kilometers	0.621	miles	mi
AREA				
mm ²	square millimeters	0.0016	square inches	in ²
m ²	square meters	10.764	square feet	ft ²
m ²	square meters	1.195	square yards	yd ²
ha	hectares	2.47	acres	ac
km ²	square kilometers	0.386	square miles	mi ²
VOLUME				
mL	milliliters	0.034	fluid ounces	fl oz
L	liters	0.264	gallons	gal
m ³	cubic meters	35.314	cubic feet	ft ³
m ³	cubic meters	1.307	cubic yards	yd ³
MASS				
g	grams	0.035	ounces	oz
kg	kilograms	2.202	pounds	lb
Mg (or "t")	megagrams (or "metric ton")	1.103	short tons (2000 lb)	T
TEMPERATURE (exact degrees)				
°C	Celsius	1.8C+32	Fahrenheit	°F
ILLUMINATION				
lx	lux	0.0929	foot-candles	fc
cd/m ²	candela/m ²	0.2919	foot-Lamberts	fl
FORCE and PRESSURE or STRESS				
N	newtons	0.225	poundforce	lbf
kPa	kilopascals	0.145	poundforce per square inch	lbf/in ²

*SI is the symbol for the International System of Units. Appropriate rounding should be made to comply with Section 4 of ASTM E380.
(Revised March 2003)

ACKNOWLEDGMENTS

This research project was performed under a pooled fund program between the State of Alaska Department of Transportation and Public Facilities, California Department of Transportation (Caltrans), Louisiana Department of Transportation and Development, Minnesota Department of Transportation, Tennessee Department of Transportation, Texas Department of Transportation and Washington State Department of Transportation, and the Federal Highway Administration. The authors acknowledge and appreciate their guidance and assistance.

Roadside Safety Research Pooled Fund Committee CONTACTS

Revised December 2008

ALASKA

Jeff Jeffers
Statewide Traffic & Safety Engineering Asst
State of Alaska Department of
Transportation and Public Facilities
3132 Channel Drive
Juneau, AK 99801
(907) 465-8962
jeff.jeffers@alaska.gov

Clint Adler, P.E.
Research Engineer
Alaska Department of Transportation and
Public Facilities
Research and Technology Transfer
2301 Peger Road
Fairbanks, AK 99709
(907) 451-5321
clint.adler@alaska.gov

Kurt Smith, P.E.
Statewide Traffic & Safety Engineer
Alaska Department of Transportation &
Public Facilities
3132 Channel Drive
Juneau, AK 99801-7898
(907) 465-6963
kurt.smith@alaska.gov

CALIFORNIA

John Jewell, P.E.
Caltrans
Office of Materials and Infrastructure
Division of Research and Innovation
5900 Folsom Blvd
Sacramento, CA 95819
(916) 227-5824
(916) 227-5856
john_jewell@dot.ca.gov

LOUISIANA

Paul Fossier
Bridge and Structural Design Section
P.O. Box 94245
Baton Rouge, LA 79084-9245
(225)379-1323
PaulFossier@dotd.louisiana.gov

Harold "Skip" Paul
Associate Director, Research
Louisiana Transportation Center
4101 Gourrier Ave.
Baton Rouge, LA 70808
(225) 767-9102
spaul@dotd.louisiana.gov

MINNESOTA

Michael Elle, P.E.
Design Standards Engineer
Minnesota Department of Transportation
395 John Ireland Blvd, MS 696
St. Paul, MN 55155
(651) 296-4859
michael.elle@dot.state.mn.us

James Klessig, Pooled Fund Manager
Minnesota Department of Transportation
Office of Investment Management
Research Services Section
395 John Ireland Blvd, MS 330
St. Paul, MN 55155
jim.klessig@dot.state.mn.us

PENNSYLVANIA

Mark R. Burkhead, P.E.
PA Department of Transportation
Bureau of Design
Highway Quality Assurance Division
400 North Street
Harrisburg, PA 17105
(717) 783-5110
www.dot.state.pa.us

TENNESSEE

Ali Hangul
Director, Design Division
Tennessee Department of Transportation
Suite 1300
James K. Polk State Office Building
Nashville, TN 37243-0348
(615) 741-0840
Ali.Hangul@state.tn.us

TEXAS

Mark A. Marek
Design Division
Texas Department of Transportation
125 East 11th Street
Austin, TX 78701-2483
(512) 416-2653
MMAREK@dot.state.tx.us

Charmaine Richardson
CRICHARD@dot.state.tx.us

WASHINGTON

Dave Olson, Chair
Design Policy, Standards,
& Research Manager
Washington State
Department of Transportation
(360) 705-7952
Olsonda@wsdot.wa.gov

Rhonda Brooks, Research Manager
Washington State Department of
Transportation
P.O. Box 47372
Olympia, WA 98504-7372
(360) 705-7945
Brookrh@wsdot.wa.gov

FEDERAL HIGHWAY ADMINISTRATION

Ken Opiela
U.S. Department of Transportation
Federal Highway Administration
Turner-Fairbanks Highway Research Center
Mail Code: HRDS-04
6300 Georgetown Pike
McLean, VA 22101
(202) 493-3371
kenneth.opiela@fhwa.dot.gov

TEXAS TRANSPORTATION INSTITUTE

D. Lance Bullard, Jr., P.E.
Research Engineer
Roadside Safety & Physical Security Div.
Texas Transportation Institute
Texas A&M University System
College Station, TX 77843-3135
(979) 845-6153
L-Bullard@tamu.edu

C. Eugene Buth, Ph.D., P.E.
Senior Research Fellow
Roadside Safety & Physical Security Div.
Texas Transportation Institute
Texas A&M University System
College Station, TX 77843-3135
(979) 845-6159
G-Buth@tamu.edu

Roger P. Bligh, Ph.D., P.E.
Research Engineer
Roadside Safety & Physical Security Div.
Texas Transportation Institute
Texas A&M University System
College Station, TX 77843-3135
(979) 845-4377
RBligh@tamu.edu

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1. INTRODUCTION	1
1.1 PROBLEM.....	1
1.2 BACKGROUND	1
1.3 OBJECTIVES AND SCOPE OF RESEARCH.....	2
2. DESIGN AND ANALYSIS	3
2.1 INTRODUCTION	3
2.2 VEHICLE MODEL	4
2.3 FREE-STANDING BARRIER WITH GROUTED REBAR-GRID SLOT CONNECTION	4
2.4 EMBEDDED BARRIER WITH GROUTED REBAR-GRID SLOT CONNECTION	10
2.5 CONCLUSIONS.....	12
3. SYSTEM DETAILS	15
3.1 TEST ARTICLE DESIGN AND CONSTRUCTION.....	15
3.2 MATERIAL SPECIFICATIONS	15
4. TEST REQUIREMENTS AND EVALUATION CRITERIA	19
4.1 CRASH TEST MATRIX.....	19
4.2 EVALUATION CRITERIA	19
5. TEST CONDITIONS.....	21
5.1 TEST FACILITY	21
5.2 VEHICLE TOW AND GUIDANCE SYSTEM.....	21
5.3 DATA ACQUISITION SYSTEMS.....	21
5.3.1 Vehicle Instrumentation and Data Processing	21
5.3.2 Anthropomorphic Dummy Instrumentation	23
5.3.3 Photographic Instrumentation and Data Processing	23
6. CRASH TEST 405160-13-1 (<i>MASH</i> TEST NO. 3-11).....	25
6.1 TEST DESIGNATION AND ACTUAL IMPACT CONDITIONS	25
6.2 TEST VEHICLE.....	25
6.3 WEATHER CONDITIONS.....	25
6.4 TEST DESCRIPTION	25
6.5 TEST ARTICLE AND COMPONENT DAMAGE	28
6.6 TEST VEHICLE DAMAGE	28
6.7 OCCUPANT RISK VALUES	28
6.8 ASSESSMENT OF TEST RESULTS.....	34
6.8.1 Structural Adequacy.....	34
6.8.2 Occupant Risk.....	34
6.8.3 Vehicle Trajectory	35

TABLE OF CONTENTS (CONTINUED)

<u>Section</u>	<u>Page</u>
7. SUMMARY AND CONCLUSIONS	37
7.1 SUMMARY	37
7.2 CONCLUSIONS.....	37
REFERENCES	41
APPENDIX A. DETAILS OF TEST ARTICLE.....	A-1
APPENDIX B. MATERIAL CERTIFICATION FOR TEST ARTICLE.....	B-1
APPENDIX C. CONCRETE INFORMATION	C-1
APPENDIX D. CRASH TEST NO. 405160-13-1.....	D-1
D1. VEHICLE PROPERTIES AND INFORMATION	D-1
D2. SEQUENTIAL PHOTOGRAPHS.....	D-4
D3. VEHICLE ANGULAR DISPLACEMENTS	D-7
D4. VEHICLE ACCELERATIONS.....	D-8

LIST OF FIGURES

	<u>Page</u>
Figure 2.1. Test installation to evaluate strength of the grouted rebar-grid connection.	5
Figure 2.2. Simulation setup for determining lateral force levels for impacts with rigid single slope barrier.	6
Figure 2.3. Lateral force comparison of pickup truck and bogie vehicle impacts on rigid single slope barrier.	6
Figure 2.4. Barrier after impact from bogie vehicle.	7
Figure 2.5. Finite element model of the bogie test.	8
Figure 2.6. Results of the bogie crash test and simulation analysis.	9
Figure 2.7. Finite element model of the 100-ft installation of free-standing single slope barrier.	9
Figure 2.8. Bogie test setup for embedded barriers.	10
Figure 2.9. Simulation and test results of bogie test with embedded barriers.	11
Figure 2.10. Simulation results with soil behind the barrier (initial (top) and final (bottom) states).	11
Figure 2.11. Simulation results with soil on both sides of barrier (initial (top) and final (bottom) states).	12
Figure 3.1. Layout of the single-slope barrier in front of 1.5:1 slope.	16
Figure 3.2. Single-slope barrier in front of 1.5:1 slope prior to testing.	17
Figure 6.1. Vehicle/installation geometrics for test 405160-13-1.	26
Figure 6.2. Vehicle before test 405160-13-1.	27
Figure 6.3. Vehicle trajectory path after test 405160-13-1.	29
Figure 6.4. Installation after test 405160-13-1.	30
Figure 6.5. Vehicle after test 405160-13-1.	31
Figure 6.6. Interior of vehicle for test 405160-13-1.	32
Figure 6.7. Summary of results for <i>MASH</i> test 3-11 on the single-slope barrier on 1.5:1 slope.	33
Figure D1. Vehicle properties for test 405160-13-1.	D-1
Figure D2. Sequential photographs for test 405160-13-1 (overhead and frontal views).	D-4
Figure D3. Sequential photographs for test 405160-13-1 (rear view).	D-6
Figure D4. Vehicle angular displacements for test 405160-13-1.	D-7
Figure D5. Vehicle longitudinal accelerometer trace for test 405160-13-1 (accelerometer located at center of gravity).	D-8
Figure D6. Vehicle lateral accelerometer trace for test 405160-13-1 (accelerometer located at center of gravity).	D-9
Figure D7. Vehicle vertical accelerometer trace for test 405160-13-1 (accelerometer located at center of gravity).	D-10
Figure D8. Vehicle longitudinal accelerometer trace for test 405160-13-1 (accelerometer located over rear axle).	D-11
Figure D9. Vehicle lateral accelerometer trace for test 405160-13-1 (accelerometer located over rear axle).	D-12
Figure D10. Vehicle vertical accelerometer trace for test 405160-13-1 (accelerometer located over rear axle).	D-13

LIST OF TABLES

	<u>Page</u>
Table 7.1. Performance evaluation summary for <i>MASH</i> test 3-11 on the single-slope barrier on slope.	39
Table D1. Exterior crush measurements for test 405160-13-1.	D-2
Table D2. Occupant compartment measurements for test 405160-13-1.	D-3

1. INTRODUCTION

1.1 PROBLEM

When concrete barriers are installed adjacent to steep slopes or on top of Mechanically Stabilized Earth (MSE) walls, a concrete moment slab is usually constructed underneath the barrier to restrict lateral barrier movement and provide barrier stability. By resisting the lateral deflection and rotation of the barrier, the moment slab prevents the barrier from toppling over the adjacent slope or the edge of the MSE wall. Moment slabs are expensive to construct and significantly increase the cost of installation. In addition to using the moment slab, several feet of soil embankment behind the barrier is generally recommended. This reduces the travel space available in front of the barrier. There is a need to develop a cost effective design for restraining the barrier and to minimize the embankment width behind the barrier.

1.2 BACKGROUND

In 1989, Texas Transportation Institute (TTI) developed the single-slope barrier for the Texas State Department of Highways and Public Transportation. (1) The development of the single-slope barrier was done under National Cooperative Highway Research Program (NCHRP) *Report 230* criteria. (2) Several full-scale crash tests were performed to evaluate the performance of the barrier. Two of the tests were conducted with the barrier in a temporary configuration. Thirty-foot, free-standing, single-slope barrier segments were connected using a rebar-grid connection (without grout) in one test and an angle-splice connection in the other test. The barriers were impacted with a 4504-lb large passenger car at a speed of 62 mph and an angle of 15 degrees in both tests. The barrier deflection in the tests with the rebar-grid connection and the angle-splice connection was 6 and 7 inches, respectively. Two more tests were performed with the single-slope barrier segments in a permanent configuration. In these tests, the 30-ft barrier segments were keyed into a 1-inch thick asphalt layer. The asphalt layer was 5 ft wide on the field side of the barrier and 1 ft wide on the traffic side. The rebar-grid connection was used to connect adjacent barriers. The connection was grouted to provide more resistance to barrier movement. The barrier was impacted with a 4504-lb large passenger car at 63.1 mph and 26.5 degrees in one test, and with an 1801-lb small passenger car at 60.7 mph and 19.9 degrees in another test. No barrier deflection was observed in either test.

It should be noted that the impact severity, which is the measure of the kinetic energy being imparted on the barrier laterally, was significantly less in the tests with the free-standing barriers when compared to the impact severity prescribed in National Cooperative Highway Research Program (NCHRP) *Report 350* and the American Association of State Highway and Transportation Officials (AASHTO) *Manual for Assessing Safety Hardware (MASH)*. (3, 4) Thus, higher deflections should be expected for the same barrier system if crash tested under *MASH* criteria. It should also be noted that most pooled fund states use barrier segments that are less than 30 ft in length. Reducing segment length is also expected to increase lateral barrier

deflection. This is because shorter segments have less mass and allow greater relative rotation of adjacent segments due to the presence of more connections.

1.3 OBJECTIVES AND SCOPE OF RESEARCH

The main objective of this research project was to develop and test a design for a restrained concrete barrier that can be placed in front of slopes as steep as 1.5H:1V, or on top of MSE walls. The design would not require a moment slab and would reduce soil embankment width behind the barrier to 2 ft or less. Further, the design feature should incorporate Washington Department of Transportation's (WSDOT) precast single slope barrier with 20-ft long barrier segments. The design was required to meet Test Level 3 (TL-3) requirements of *MASH*.

The existing WSDOT single slope barrier uses a grouted rebar-grid connection to connect the 20-ft long barrier segments. The performance of this barrier connection was not known in a free standing condition. It was suggested that if the free standing barrier with grouted rebar-grid connection resulted in small lateral deflection under vehicle impact, it would render the simplest and most cost effective solution to the design problem. The researchers evaluated the performance of this connection in a free-standing single-slope barrier using a surrogate bogie vehicle impact test and finite element analysis. It was determined that using the barrier with existing connection in a free-standing mode would result in large lateral deflections.

The researchers then evaluated restraining the barrier by embedding it 10 inches in soil and providing a 2 ft offset from the slope breakpoint. Another phase of bogie testing and finite element analysis was performed and it was determine that the design would result in acceptable lateral deflection. Subsequently, the new embedded barrier design was crash tested and it successfully met *MASH* TL-3 requirements. The maximum static deflection of the barrier was 5.5 inches.

Details of the design and analysis are presented in chapter 2 of this report. Chapter 3 presents the description of the test article. Details of the testing criteria and crash test results are presented in chapters 4 through 6. Chapter 7 presents a summary of the results, conclusions, and recommendations emanating from this project.

2. DESIGN AND ANALYSIS

2.1 INTRODUCTION

The primary objective of this research was to develop a design for a precast concrete barrier that can be placed in front of slopes as steep as 1.5H:1V or on top of MSE walls, without using a moment slab. The design was required to use 20-ft long single-slope barrier segments, and to restrict the soil embankment behind the barrier to two feet or less.

The pooled-fund states typically use the grouted rebar-grid slot connection to connect single-slope barrier segments. To date, there has been no testing performed with the single slope barrier using the grouted rebar-grid slot connection in a free-standing condition. As a first step, the researchers evaluated the performance of the free-standing single slope barrier. The objective of this evaluation was to determine if the grouted rebar-grid connection provided sufficient connection strength to cause adjacent barriers segments to deflect as a single body during vehicle impact, without significant rotation at the joints. If this could be achieved, it was believed that the impacting vehicle can be contained and redirected without significant barrier deflection simply using the weight of the concrete barrier. This would have also rendered the easiest solution to the design problem and allowed maximum flexibility in the use of the barrier. However, subsequent evaluation of the grouted rebar-grid slot connection in a free-standing condition showed that it is not strong enough to transfer moments between adjacent barrier segments and results in large rotations at the joints, thus resulting in a large overall lateral barrier deflection.

The researchers then considered use of different methods for restraining the barrier to prevent large lateral deflection. Among the methods considered were using a stronger barrier connection, pinning or staking the barrier segments with steel pins, using straps or angles to tie adjacent barriers together, etc. However, the participating states expressed interest in keeping the same connection methods and avoiding use of additional hardware if possible. To fulfill these requirements, the researchers evaluated restraining the barriers by embedding them in soil. The height of a typical single-slope barrier is 42 inches. The researchers suggested embedding the single slope barrier 10 inches in soil. This reduces the height of the barrier to 32 inches, which is typical of the common New Jersey and F-shape barrier profiles. The researchers used a combination of component level bogie impact testing, simulation analysis, and full-scale crash testing¹ to successfully develop a restraint mechanism for the single slope barrier by embedding it 10 inches in soil. The design uses existing grouted rebar-grid slot connection and requires a 2-ft offset from the slope breakpoint. Details of the analysis are presented in later sections of this chapter. Details of the final design and the results of the full-scale crash testing are presented in subsequent chapters of this report.

¹ The bogie testing and the full-scale crash test reported herein were performed at TTI Proving Ground. TTI Proving Ground is an ISO 17025 accredited laboratory with A2LA Mechanical Testing certificate 2821.01. This certificate does not include simulation analysis.

2.2 VEHICLE MODEL

In *MASH*, which is a recent update to the *NCHRP Report 350*, the pickup truck design vehicle has been changed from a 4409-lb, $\frac{3}{4}$ -ton, standard cab pickup truck to a 5000-lb, $\frac{1}{2}$ -ton, 4-door pickup truck. While a public domain finite element model of the 4409-lb pickup truck was available to researchers in the roadside safety community, no such model was available for the 5000-lb, $\frac{1}{2}$ -ton, 4-door pickup truck during the period of this research. The Federal Highway Administration (FHWA) had funded the development of a finite element model for a $\frac{1}{2}$ -ton, Chevrolet Silverado, 4-door, pickup truck, which meets the design test vehicle requirements of *MASH*. However, the work on developing this new model was underway but was not completed within the timeframe of this research.

In the past, TTI researchers have made simple modifications to the existing 4409-lb pickup truck model for use in studies where the dynamics of the vehicle were not very critical compared to the higher mass required by *MASH*. These modifications involve increasing the mass of the existing 4409-lb pickup truck model by distributing additional mass over different parts of the vehicle and bringing the total vehicle mass to 5000-lb. The original 4409-lb pickup truck model was developed by the National Crash Analysis Center with further modifications and improvements by TTI researchers.

In the absence of a pickup truck model that met *MASH* requirements, the researchers employed the above mentioned methodology of using a surrogate 5000-lb pickup truck model for evaluating the single-slope barrier design. Doing so enabled the researchers to impart the same level of impact energy into the barrier system as required by *MASH*. It was expected that the vehicle dynamics response of the surrogate 5000-lb vehicle will not match the response measured in a crash test. However, previous testing of the single-slope barrier has shown that the vehicle remains fairly stable during the impact. (1) Thus the vehicle dynamic characteristics were not deemed as critical and accounting for the increased vehicle mass was expected to enable a successful evaluation of the barrier system for the *MASH* criteria.

2.3 FREE-STANDING BARRIER WITH GROUTED REBAR-GRID SLOT CONNECTION

To evaluate the performance of the free-standing single slope barrier with grouted rebar-grid connection, the researchers first determined the dynamic response of a single barrier connection using bogie testing. Two 42-inch tall, 20-ft long single-slope barrier segments were connected using the WSDOT grouted rebar-grid connection. The free ends of the barrier segments were constrained from moving laterally by a 5-inch diameter pipe that was anchored to the concrete pavement as shown in figure 2.1. A 5000-lb surrogate bogie vehicle impacted the barrier connection at a 90 degree angle. The purpose of this bogie test was to evaluate the strength of the grouted rebar-grid connection when used with the single-slope barrier in a free-standing condition. The test results were later used to calibrate a model of the grouted rebar-grid slot connection for further evaluation of the overall barrier system performance.




Figure 2.1. Test installation to evaluate strength of the grouted rebar-grid connection.

An appropriate impact speed of the bogie vehicle was determined using simulation analysis. A simulation was performed with the 5000-lb pickup truck vehicle impacting a rigid single slope barrier at 62 mi/h and 25 degree angle (as required by test 3-11 of *MASH*. See figure 2.2). The force of contact between the vehicle and rigid barrier were measured. Another set of simulations was performed where a finite element model of the 5000-lb surrogate bogie vehicle impacted a rigid single slope barrier at 90 degrees (as shown in figure 2.2). The contact force between the bogie vehicle and the rigid barrier were measured for several impact speeds and then compared to the forces resulting from the pickup truck impact with the barrier (as shown in figure 2.3). The comparison revealed that a 15 mi/h impact at 90 degrees provided forces that were approximately equivalent to those resulting from a 62 mi/h impact of the pickup at 25 degrees. Thus, the impact speed of the bogie vehicle in the test was selected to be 15 mi/h.

The 5000-lb bogie vehicle impacted the barriers at the center of the joint at an impact speed of 14 mi/h. The impact in the test resulted in a maximum permanent lateral deflection of 22 inches. The grouted rebar-grid connection cracked near the centerline of the connection (see figure 2.4).




Figure 2.2. Simulation setup for determining lateral force levels for impacts with rigid single slope barrier.




Figure 2.3. Lateral force comparison of pickup truck and bogie vehicle impacts on rigid single slope barrier.



Figure 2.4. Barrier after impact from bogie vehicle.

The researchers then developed a finite element model of the barrier installation used in the bogie test. The single slope barrier segments were modeled with mostly rigid material representation. To improve the distribution of forces at interfaces between adjacent barriers and between the barrier and the ground, elastic material representation was used in these regions. The grouted rebar-grid connection was modeled using bi-linear elastic-plastic material and a rebar-grid comprised of beam elements. A 5000-lb bogie vehicle model impacted the barrier model at the test speed and location. The model of the barrier bogie test setup is shown in figure 2.5.




Figure 2.5. Finite element model of the bogie test.

The properties of the surrogate grouted rebar-grid connection in the simulation model were calibrated to match the lateral deflection of the barrier observed in the test. Figure 2.6 shows the calibrated simulation results compared to the crash test results.

Once the response of a single grouted rebar-grid connection was calibrated, the researchers developed a 100-ft long full-scale barrier system model to evaluate the free-standing single slope barrier under *MASH* TL-3 impact conditions (i.e. impact with a 5000-lb vehicle at 62 mi/h and 25 degrees). The objective of this simulation was to determine if the overall lateral deflection of the free-standing barrier installation was small enough to allow its use adjacent to slopes or on MSE walls without requiring any restraining mechanisms. The barrier system model was comprised of five 20-ft long single slope barrier segments that were connected using the calibrated grouted rebar-grid slot connection model. The 5000-lb vehicle impacted the barrier 4 ft upstream of the connection between the second and the third barrier segment as shown in figure 2.7.

In the simulated impact, the free standing barrier had a deflection greater than 30 inches. This deflection was much higher than acceptable as per the objectives of this research. Hence, the researchers started investigating ways of restraining the barrier to limit lateral deflections.




Figure 2.6. Results of the bogie crash test and simulation analysis.




Figure 2.7. Finite element model of the 100-ft installation of free-standing single slope barrier.

2.4 EMBEDDED BARRIER WITH GROUTED REBAR-GRID SLOT CONNECTION

Various methods of restraining the barriers were considered, such as anchoring with steel pins, using steel straps to tie barrier segments, etc. In consultation with the technical representatives of the participating pooled fund states, it was decided to investigate direct embedment of the barrier in soil. This method allowed the use of existing hardware inventory without any modifications. The embedment depth was 10 inches. A typical single slope barrier used by the sponsoring pooled fund states is 42 inches tall. The states did not perceive any related problems with reducing the effective height of the single slope barrier to 32 inches as a result of the 10-inch embedment. The 32-inch barrier height is typical for other commonly used safety shape barriers such as the New Jersey and the F-shape barriers.

The researchers conducted another bogie impact test with two single-slope barrier segments connected via grouted rebar-grid slot connection and embedded 10 inches in soil. The width of the soil behind the barrier was 24 inches behind the barrier. A 1.5H:1V slope was used for the soil cut, as shown in the test setup in figure 2.8. The type of soil and the compaction method used were as specified in the *MASH* guidelines. The 5004-lb bogie vehicle impacted the barrier at the joint at a speed of 14.4 mi/h. The maximum permanent barrier deflection was 4.45 inches at the joint. The researchers then incorporated a 10-inch soil layer into the finite element model and calibrated the soil properties by conducted bogie vehicle impact simulations until the results matched the barrier deflection observed in the test (see figure 2.9).




Figure 2.8. Bogie test setup for embedded barriers.




Figure 2.9: Simulation and test results of bogie impacted with embedded barriers.

The researchers used the calibrated embedded barrier to develop a 100-ft long full-scale barrier system model. The installation was comprised of five 20-ft long single-slope barrier segments, connected using grouted rebar-grid connection and embedded 10 inches in soil behind the barrier (i.e. on the field side). The field side of the barriers was offset 2 ft from the 1.5H:1V slope. A simulation was performed with a 5000-lb vehicle impacting the barrier at 25 degrees and 62 mi/h (see figure 2.10). The vehicle impacted the barrier 4 ft upstream of the connection between the second and the third barrier segment. The vehicle was successfully contained and redirected by the embedded barrier system. The maximum permanent deflection of the barrier was 10 inches. The deflection of the barrier after the impact is shown in figure 2.10.




Figure 2.10: Simulation results with soil behind the barrier (initial (top) and final (bottom) states).

As mentioned above, in the initial simulation the soil was present only behind the barrier, to match the bogie test configuration. Thus, the effective height of the barrier remained 42 inches for the impacting vehicle. A field installation of the embedded barrier can involve scenarios when the barrier is embedded in soil both in front and back of the barrier. In this case, the effective height of the barrier for the impacting vehicle is reduced to 32 inches, which could result in greater vehicular instability. Presence of the soil in front and back of the barrier is expected to lower the lateral barrier deflection slightly, which would be desirable for this design. To quantify the differences between the two installation scenarios, the researchers performed another simulation where soil was added to the front of the barrier as well. The mass of the vehicle and the impact conditions remained the same. Simulation results showed that the maximum permanent deflection of the barrier in this case was 9.75 inches (see figure 2.11). When compared to the previous simulation, the reduction in lateral barrier deflection was insignificant. Even though the vehicle was redirected successfully in both simulations, slightly greater vehicle roll was observed when the barrier was installed with soil on both sides (i.e. when the effective barrier height was reduced to 32 inches).




Figure 2.11. Simulation results with soil on both sides of barrier (initial (top) and final (bottom) states).

2.5 CONCLUSIONS

Using a combination of bogie testing and simulation analysis, the researchers determined that the free standing single slope barrier with the grouted rebar-grid slot connection cannot provide adequate lateral resistance to allow its use adjacent to 1.5H:1V slopes or on MSE walls when the offset behind the barrier is 2 ft or less. Simulation results indicated that the free-standing barrier is likely to result in lateral deflection of greater than 30 inches, which is significantly more than the desired deflection for this project.

The researchers then evaluated a single slope barrier embedded 10 inches in soil. In this case, the lateral deflection of the barrier was significantly reduced. The embedded barrier was evaluated both with the soil present in front and behind the barrier, and with soil present only behind the barrier. Simulation results indicated that the vehicle was successfully contained and

redirected in both cases and the requirement of reduced lateral deflection was met. In the case when soil was present on both sides of the barrier, higher vehicle roll was observed. This was expected because the barrier embedment reduced the height of the barrier from 42 inches to 32 inches. Based on these results, the researchers recommended that the crash test be performed on a single slope barrier using grouted rebar-grid connection embedded 10 inches in soil on both sides. This was considered to be the more critical configuration in regard to impact performance. Thus, a successful test could validate the use of both configurations.

3. SYSTEM DETAILS

3.1 TEST ARTICLE DESIGN AND CONSTRUCTION

The test article was comprised of a 100-ft long installation of single-slope concrete barrier embedded 10 inches in soil. Five 20-ft long barrier segments were connected using the grouted rebar-grid slot connections to achieve the 100-ft installation length.

The single-slope barrier segments were 42 inches tall, 24 inches wide at the base and 8 inches wide at the top. At each end of the barrier segments, a 3-inch wide, 24-inch deep, and 10.5-inch long slot was cast into the barrier to accommodate the grouted rebar-grid connection. The concrete reinforcement of the barrier segments was comprised of #4 vertical bars that were bent to approximately match the profile of the barrier faces and were spaced 12 inches apart along the length of the barrier. The spacing of the vertical bars was reduced around the slot cast at each end for the grouted rebar-grid connection. The vertical bars, ten #5 longitudinal bars were located along the height of the barrier. A 4-inch wide, 2-inch high slot was cast at the bottom of the segments along their centerline.

The barrier was embedded in crushed limestone road base material that conforms to *MASH* standard soil. To embed the barrier to a depth of 2-ft, the native soil adjacent to the testing facility's concrete pavement was excavated. The excavated area was then backfilled with standard *MASH* soil and compacted in approximately 6-inch lifts. Once the backfill soil reached a level of 10 inches below the concrete pavement surface, the barrier was set in place and further soil was added and compacted in front and back of the barrier. As the soil was backfilled, a 1.5H:1V slope was built into the embankment with the breakpoint located 2 ft from the field side of the barrier.

A rebar-grid was then dropped into the slot at each barrier connection location. It was comprised of two vertical #6 bars that were spaced 10 inches apart, and three longitudinal #8 bars that were spaced eight inches apart. With the rebar-grid in place, the connection was grouted using a non-shrink grout.

Details of the test article are shown in figures 3.1 and 3.2, and Appendix A.

3.2 MATERIAL SPECIFICATIONS

The barrier concrete was specified to have a minimum 28-day compressive strength of 4000 psi. The reinforcing steel was specified to be grade 60. The steel material used for manufacturing the rebar-grid was also specified to be grade 60 (see appendix B for MIL certificates). The grout used for making the connection was Shelper #1107 non-shrink grout which had a minimum compressive strength of 4000 psi (see appendix C for compressive strength test results). The soil used for embedding the barriers was a crushed limestone road base material that conforms to standard *MASH* soil. The moisture content of the soil on the day of the test was 8.5%.




Figure 3.1. Layout of the single-slope barrier in front of 1.5:1 slope.



Figure 3.2. Single-slope barrier in front of 1.5:1 slope prior to testing.

4. TEST REQUIREMENTS AND EVALUATION CRITERIA

4.1 CRASH TEST MATRIX

According to *MASH*, two tests are recommended to evaluate longitudinal barriers to test level three (TL-3) as described below.

***MASH* Test Designation 3-10:** A 2425 lb vehicle impacting the critical impact point (CIP) of the length of need section at a speed of 62 mi/h and an angle of 25 degrees.

***MASH* Test Designation 3-11:** A 5000 lb pickup truck impacting the CIP of the length of need section at a speed of 62 mi/h and an angle of 25 degrees.

The researchers performed test 3-11 of *MASH* (5000 lb vehicle, 62 mi/h, 25 degrees) on the embedded single-slope barrier system. It is argued that this is the critical test for this design and the test with smaller 2425 lb vehicle is not needed. Due to higher impact energy, the test with the 5000 lb pickup truck will result in greater impact load on the connections and greater lateral deflection. An impact resulting from the lighter 2425 lb passenger car under same impact speed and angle will not result in any increase in lateral deflection of the barrier nor will it impart a higher force on the barrier to evaluate connection strength and barrier rotation. Due to the small deflection expected in the test, the small car impact with the embedded single-slope barrier is expected to be similar to an impact into a rigid single-slope barrier. Thus, the test was conducted with the 5000 lb pickup only.

The crash test and data analysis procedures were in accordance with guidelines presented in *MASH*. Chapter 5 presents brief descriptions of these procedures.

4.2 EVALUATION CRITERIA

The crash test was evaluated in accordance with the criteria presented in *MASH*. The performance of the barrier is judged on the basis of three factors: structural adequacy, occupant risk, and post impact vehicle trajectory. Structural adequacy is judged upon the barrier's ability to contain and redirect the vehicle, or bring the vehicle to a controlled stop in a predictable manner. Occupant risk criteria evaluate the potential risk of hazard to occupants in the impacting vehicle, and to some extent other traffic, pedestrians, or workers in construction zones, if applicable. Post impact vehicle trajectory is assessed to determine potential for secondary impact with other vehicles or fixed objects, creating further risk of injury to occupants of the impacting vehicle and/or risk of injury to occupants in other vehicles. The appropriate safety evaluation criteria from table 5.1 of *MASH* were used to evaluate the crash test reported herein, and are listed in further detail under the assessment of the crash test.

5. TEST CONDITIONS

5.1 TEST FACILITY

The full-scale crash test was performed at Texas Transportation Institute (TTI) Proving Ground. TTI Proving Ground is an International Standards Organization (ISO) 17025 accredited laboratory with American Association for Laboratory Accreditation (A2LA) Mechanic Testing certificate 2821.01. The full-scale crash test was performed according to TTI Proving Ground quality procedures and according to the *MASH* guidelines and standards.

The test facilities at the TTI Proving Ground consist of a 2000 acre complex of research and training facilities situated 10 mi northwest of the main campus of Texas A&M University. The site, formerly an Air Force Base, has large expanses of concrete runways and parking aprons well suited for experimental research and testing in the areas of vehicle performance and handling, vehicle-roadway interaction, durability and efficacy of highway pavements, and safety evaluation of roadside safety hardware. The site selected for the placement of the barrier was along a wide out-of-service apron. The apron consists of an unreinforced jointed concrete pavement in 12.5 ft x 15 ft blocks nominally 8-12 inches deep. The apron is over 50 years old and the joints have some displacement, but are otherwise flat and level.

5.2 VEHICLE TOW AND GUIDANCE SYSTEM

The test vehicle was towed into the test installation using a steel cable guidance and reverse tow system. A steel cable for guiding the test vehicle was tensioned along the path, anchored at each end, and threaded through an attachment to the front wheel of the test vehicle. An additional steel cable was connected to the test vehicle, passed around a pulley near the impact point, through a pulley on the tow vehicle, and then anchored to the ground such that the tow vehicle moved away from the test site. A two-to-one speed ratio between the test and tow vehicle existed with this system. Just prior to impact with the installation, the test vehicle was released to be free-wheeling and unrestrained. The vehicle remained free-wheeling, i.e., no steering or braking inputs, until the vehicle cleared the immediate area of the test site, at which time brakes on the vehicle were activated to bring it to a safe and controlled stop.

5.3 DATA ACQUISITION SYSTEMS

5.3.1 Vehicle Instrumentation and Data Processing

The test vehicle was instrumented with three solid-state angular rate transducers to measure roll, pitch, and yaw rates; a triaxial accelerometer near the vehicle center of gravity (c.g.) to measure longitudinal, lateral, and vertical acceleration levels; and a backup biaxial accelerometer in the rear of the vehicle to measure longitudinal and lateral acceleration levels. These accelerometers were ENDEVCO[®] Model 2262CA, piezoresistive accelerometers with a ± 100 g range.

The accelerometers are strain gage type with a linear millivolt output proportional to acceleration. Angular rate transducers are solid state, gas flow units designed for high-“G” service. Signal conditioners and amplifiers in the test vehicle increase the low-level signals to a ± 2.5 volt maximum level. The signal conditioners also provide the capability of an R-cal (resistive calibration) or shunt calibration for the accelerometers and a precision voltage calibration for the rate transducers. The electronic signals from the accelerometers and rate transducers are transmitted to a base station by means of a 15-channel, constant-bandwidth, Inter-Range Instrumentation Group (IRIG), FM/FM telemetry link for recording and for display. Calibration signals from the test vehicle are recorded before the test and immediately afterwards. A crystal-controlled time reference signal is simultaneously recorded with the data. Wooden dowels actuate pressure-sensitive switches on the bumper of the impacting vehicle prior to impact to indicate the elapsed time over a known distance to provide a measurement of impact velocity. The initial contact also produces an “event” mark on the data record to establish the instant of contact with the installation.

The multiplex of data channels, transmitted on one radio frequency, is received and demultiplexed onto TEAC[®] instrumentation data recorder. After the test, the data are played back from the TEAC[®] recorder and digitized. A proprietary software program (WinDigit) converts the analog data from each transducer into engineering units using the R-cal and pre-zero values at 10,000 samples per second, per channel. WinDigit also provides Society of Automotive Engineers (SAE) J211 class 180 phaseless digital filtering and vehicle impact velocity.

All accelerometers are calibrated annually according to the (SAE) J211 4.6.1 by means of an ENDEVCO[®] 2901, precision primary vibration standard. This device and its support instruments are returned to the factory annually for a National Institute of Standards Technology (NIST) traceable calibration. The subsystems of each data channel are also evaluated annually, using instruments with current NIST traceability, and the results are factored into the accuracy of the total data channel, per SAE J211. Calibrations and evaluations are made any time data are suspect.

The Test Risk Assessment Program (TRAP) uses the data from WinDigit to compute occupant/compartiment impact velocities, time of occupant/compartiment impact after vehicle impact, and the highest 10-milliseconds (ms) average ridedown acceleration. WinDigit calculates change in vehicle velocity at the end of a given impulse period. In addition, maximum average accelerations over 50-ms intervals in each of the three directions are computed. For reporting purposes, the data from the vehicle-mounted accelerometers are filtered with a 60-Hz digital filter, and acceleration versus time curves for the longitudinal, lateral, and vertical directions are plotted using TRAP.

TRAP uses the data from the yaw, pitch, and roll rate transducers to compute angular displacement in degrees at 0.0001-s intervals and then plots yaw, pitch, and roll versus time. These displacements are in reference to the vehicle-fixed coordinate system with the initial position and orientation of the vehicle-fixed coordinate systems being initial impact.

5.3.2 Anthropomorphic Dummy Instrumentation

Use of a dummy in the 2270P vehicle is optional according to *MASH*, and there was no dummy used in the test with the 2270P vehicle.

5.3.3 Photographic Instrumentation and Data Processing

Photographic coverage of the test included three high-speed cameras: one overhead with a field of view perpendicular to the ground and directly over the impact point; one placed behind the installation at an angle; and a third placed to have a field of view parallel to and aligned with the installation at the downstream end. A flashbulb activated by pressure-sensitive tape switches was positioned on the impacting vehicle to indicate the instant of contact with the installation and was visible from each camera. The films from these high-speed cameras were analyzed on a computer-linked motion analyzer to observe phenomena occurring during the collision and to obtain time-event, displacement, and angular data. A mini-DV camera and still cameras recorded and documented conditions of the test vehicle and installation before and after the test.

6. CRASH TEST 405160-13-1 (MASH TEST NO. 3-11)

6.1 TEST DESIGNATION AND ACTUAL IMPACT CONDITIONS

MASH test 3-11 involves a 2270P vehicle weighing 5000 lb \pm 100 lb and impacting the barrier at an impact speed of 62.2 mi/h \pm 2.5 mi/h and an angle of 25 degrees \pm 1.5 degrees. The target impact point was 4 ft upstream of the centerline of the joint located between segments 2 and 3. The 2002 Dodge pickup used in the test weighed 4953 lb and the actual impact speed and angle were 63.1 mi/h and 24.2 degrees, respectively. The actual impact point was 62.0 inches upstream of the joint between segments 2 and 3.

6.2 TEST VEHICLE

A 2002 Dodge Ram 1500 quad-cab pickup, shown in figures 6.1 and 6.2, was used for the crash test. Test inertia weight of the vehicle was 4953 lb. The height to the lower edge of the vehicle's front bumper was 13.5 inches, and the height to the upper edge of the front bumper was 26.0 inches. The height to the center of gravity was 28.12 inches. Additional dimensions and information on the vehicle are given in appendix D, figure D1. The vehicle was directed into the installation using the cable reverse tow and guidance system, and was released to be free-wheeling and unrestrained just prior to impact.

6.3 WEATHER CONDITIONS

The crash test was performed the morning of April 16, 2009. Weather conditions at the time of testing were: Wind speed: 7 mi/h; wind direction: 90 degrees with respect to the vehicle (vehicle was traveling in a southwesterly direction); temperature: 70 °F; relative humidity: 71 percent.

6.4 TEST DESCRIPTION

The 2270P vehicle, traveling at an impact speed of 63.1 mi/h, impacted the single-slope barrier 62 inches upstream of the joint between segments 2 and 3, at an impact angle of 24.2 degrees. At approximately 0.042 s, the right front tire began to climb the face of the barrier and the vehicle began to redirect. At 0.169 s, the vehicle was parallel to the barrier and was traveling at a speed of 58.7 mi/h. At 0.173 s, the right rear of the vehicle contacted the barrier, and at 0.176 s, the vehicle began to roll clockwise. The right rear corner of the bed of the vehicle contacted the top of the barrier at 0.616 s, and after that, dust obscured the view in all camera views. Brakes on the vehicle were applied 1.5 s after impact, and the vehicle came to rest 247 ft downstream of impact and 10 ft toward traffic lanes. Sequential photographs of the test period are shown in appendix D, figures D2 and D3.



Figure 6.1. Vehicle/installation geometrics for test 405160-13-1.



Figure 6.2. Vehicle before test 405160-13-1.

6.5 TEST ARTICLE AND COMPONENT DAMAGE

Damage to the barrier is shown in figures 6.3 and 6.4. Tire marks were observed on the traffic face of the barrier and there was no evidence of cracking in the barrier. Length of contact of the vehicle with the barrier was 14.0 ft. Maximum permanent deflection of the barrier was 5.5 inches. Working width was 19.6 inches. Maximum dynamic deflection during the test was 5.6 inches.

6.6 TEST VEHICLE DAMAGE

The 2270P vehicle sustained damage to the right front corner and along the right side, as shown in figure 6.5. The right upper A-arm, right tie rod end, and sway bar were deformed. Also damaged were the front bumper, grill, right front fender, right front and rear doors, right exterior side of bed, rear bumper, and tailgate. The right front and rear wheel rims were deformed and the right front tire was deflated. Maximum exterior crush to the vehicle was 14.0 inches in the side plane at the right front corner at bumper height. Maximum occupant compartment deformation was 0.5 inches in the right front door at hip height. Photographs of the interior of the vehicle are shown in figure 6.6. Exterior vehicle crush and occupant compartment measurements are shown in appendix D, tables D1 and D2.

6.7 OCCUPANT RISK VALUES

Data from the accelerometer, located at the vehicle's center of gravity, were digitized for evaluation of occupant risk. In the longitudinal direction, the occupant impact velocity was 12.1 ft/s (3.7 m/s) at 0.090 s, the highest 0.010-s occupant ridedown acceleration was -2.4 Gs from 0.173 to 0.183 s, and the maximum 0.050-s average acceleration was -6.5 Gs between 0.009 and 0.059 s. In the lateral direction, the occupant impact velocity was 24.6 ft/s (7.5 m/s) at 0.090 s, the highest 0.010-s occupant ridedown acceleration was -11.3 Gs from 0.187 to 0.197 s, and the maximum 0.050-s average was -13.0 Gs between 0.026 and 0.076 s. Theoretical Head Impact Velocity (THIV) was 29.6 km/h or 8.2 m/s at 0.089 s; Post-Impact Head Decelerations (PHD) was 11.3 Gs between 0.187 and 0.197 s; and Acceleration Severity Index (ASI) was 1.56 between 0.020 and 0.070 s. These data and other pertinent information from the test are summarized in figure 6.7. Vehicle angular displacements and accelerations versus time traces are presented in appendix D, figures D4 through D10.



Figure 6.3. Vehicle trajectory path after test 405160-13-1.



Figure 6.4. Installation after test 405160-13-1.



Figure 6.5. Vehicle after test 405160-13-1.




Before Test



After Test

Figure 6.6. Interior of vehicle for test 405160-13-1.



33

General Information

Test Agency..... Texas Transportation Institute
 Test No. 405160-13-1
 Date April 16, 2009

Test Article

Type..... Concrete Barrier
 Name Single-Slope Barrier offset 2 ft from 1.5:1 Slope
 Installation Length 100 ft
 Material or Key Elements 42-inch tall x 20 ft long single-slope concrete barrier embedded 10 inches in soil in front of 1.5H:1V slope

Soil Type and Condition

Standard Soil, Dry

Test Vehicle

Type/Designation..... 2270P
 Make and Model 2002 Dodge Ram 1500 Pickup
 Curb 4630 lb
 Test Inertial 4953 lb
 Dummy No Dummy
 Gross Static 4953 lb

Impact Conditions

Speed63.1 mi/h
 Angle24.2 degrees
 Location/Orientation62 inch upstrm Joint 2-3

Exit Conditions

SpeedOut of view
 AngleOut of view

Occupant Risk Values

Impact Velocity
 Longitudinal12.1 ft/s
 Lateral24.6 ft/s
 Ridedown Accelerations
 Longitudinal -2.4 G
 Lateral-11.3 G
 THIV 29.6 km/h
 PHD 11.3 G
 Max. 0.050-s Average
 Longitudinal -6.5 G
 Lateral-13.0 G
 Vertical -4.2 G

Post-Impact Trajectory

Stopping Distance 247 ft dwnstrm
 10 ft fwd

Vehicle Stability

Maximum Yaw Angle.....-42 degrees
 Maximum Pitch Angle.....-11 degrees
 Maximum Roll Angle..... 44 degrees
 Vehicle Snagging..... No
 Vehicle Pocketing..... No

Test Article Deflections

Dynamic..... 5.6 inches
 Permanent 5.5 inches
 Working Width 19.6 inches

Vehicle Damage

VDS 01RFQ5
 CDC..... 01RFEW4
 Max. Exterior Deformation..... 14.0 inches
 Max. Occupant Compartment Deformation..... 0.56 inch

Figure 6.7. Summary of results for MASH test 3-11 on the single-slope barrier on 1.5:1 slope.

6.8 ASSESSMENT OF TEST RESULTS

An assessment of the test was made based on the following applicable *MASH* safety evaluation criteria.

6.8.1 Structural Adequacy

- A. *Test article should contain and redirect the vehicle or bring the vehicle to a controlled stop; the vehicle should not penetrate, underride, or override the installation, although controlled lateral deflection of the test article is acceptable.*

Results: The single-slope barrier in front of 1.5H:1V slope contained and redirected the 2270P vehicle. The vehicle did not penetrate, underride, or override the installation. Maximum dynamic deflection during the test was 5.6 inches. (PASS)

6.8.2 Occupant Risk

- D. *Detached elements, fragments, or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformation of, or intrusions into, the occupant compartment should not exceed limits set forth in Section 5.3 and Appendix E of MASH.*

Results: No detached elements, fragments, or other debris were present to penetrate or show potential to penetrate the occupant compartment, or to present undue hazard to others in the area. (PASS)
Maximum occupant compartment deformation was 5.5 inches. (PASS)

- F. *The vehicle should remain upright during and after collision. The maximum roll and pitch angles are not to exceed 75 degrees.*

Results: The 2270P vehicle remained upright during and after the collision event. Maximum roll was 44 degrees. (PASS)

- H. *Occupant impact velocities should satisfy the following:*

Longitudinal and Lateral Occupant Impact Velocity

<u>Preferred</u>	<u>Maximum</u>
9.0 m/s (30 ft/s)	12.2 m/s (40 ft/s)

Results: Longitudinal occupant impact velocity was 12.1 ft/s, and lateral occupant impact velocity was 24.6 ft/s. (PASS)

- I. *Occupant ridedown accelerations should satisfy the following:*

Longitudinal and Lateral Occupant Ridedown Accelerations

<u>Preferred</u>	<u>Maximum</u>
15.0 Gs	20.49 Gs

Results: Longitudinal ridedown acceleration was -2.4 G, and lateral ridedown acceleration was -11.3 G. (PASS)

6.8.3 Vehicle Trajectory

For redirective devices, the vehicle shall exit the barrier within the exit box.

Result: The vehicle exited within the exit box. (PASS)

7. SUMMARY AND CONCLUSIONS

7.1 SUMMARY

To restrict the lateral deflection of a single slope barrier when placed adjacent to 1.5H:1V slope or on top of an MSE wall, a 100-ft installation of the barrier was embedded 10 inches in soil. The effective height of the single slope barrier was thus reduced to 32 inches due to the 10 inch embedment. The barrier was placed at a 2-ft lateral offset from the 1.5H:1V slope break point of the soil embankment. The concrete barrier was comprised of five 20-ft long barrier segments that were connected using the grouted rebar-grid connection. The embedded barrier was crash tested using *MASH* test level 3 criteria.

The embedded single-slope barrier successfully contained and redirected the 2270P vehicle. The vehicle did not penetrate, underide, or override the installation. Maximum dynamic and static deflections of the barrier during the test were 5.6 inches and 5.5 inches, respectively. No detached elements, fragments, or other debris were present to penetrate or show potential to penetrate the occupant compartment, or to present undue hazard to others in the area. Maximum occupant compartment deformation was 5.5 inches. The 2270P vehicle remained upright during and after the collision event. Maximum roll was 44 degrees. Occupant risk factors were within the limits specified in *MASH*. The vehicle remained within the exit box.

7.2 CONCLUSIONS

The objective of this research was to restrict lateral deflection of the barrier when placed adjacent to steep slopes such as 1.5H:1V or on top of MSE walls, without using a concrete moment slab.

The final design was required to incorporate 20-ft long single slope barrier segments with grouted rebar grid connection. Since the performance of the grouted rebar-grid connection in a free-standing single slope barrier was not known under *MASH* evaluation criteria, the researchers evaluated its performance using a smaller scale bogie impact test and simulation analysis. It was determined that the grouted rebar grid connection did not provide enough strength to restrict lateral deflections to acceptable levels for this application. Results of the simulation analysis showed that large lateral deflection was expected with the grouted rebar-grid connection when used with the single slope barrier in a free-standing mode.

The researchers then evaluated restricting the deflection of the barrier by embedding it 10 inches in soil. The barrier was placed in front of a 1.5H:1V slope. The offset of the barrier from the slope break point of the soil embankment was restricted to two feet. Another phase of bogie testing and simulation analysis was performed to evaluate the performance of the grouted rebar grid connection in the embedded barrier configuration. Results of the simulation analysis showed that the embedded barrier system will result in acceptably reduced lateral deflections.

The researchers performed simulations of the 100-ft long installation of the embedded barrier with soil present in front and behind the barrier, and with soil present only behind the barrier. Both configurations resulted in a successful redirection of the vehicle. It was determined that there were no significant differences in the lateral barrier deflection resulting from these two configurations. However, simulation results indicated that due to the reduced effective height of the barrier when soil layer is present in front of the barrier, the vehicle exhibited slightly higher climb and roll. Thus the researchers recommended performing the crash test in the configuration where soil is present in front and behind the barrier.

A full-scale crash test was subsequently performed to validate the design. The embedded single-slope barrier in front of 1.5H:1V slope performed acceptably according to the requirements of *MASH*, as shown in table 7.1. The permanent lateral deflection of the barrier was 5.5 inches.

Based on the successful test of the embedded barrier with soil present in front and behind the barrier, the configuration with soil present only behind the barrier is also considered acceptable provided proper placement and compaction of the soil behind the barrier is achieved. While the embedded barrier design was tested in front of a 1.5H:1V slope, due to the small lateral barrier deflection, it is also considered suitable for use on top of an MSE wall.

Table 7.1. Performance evaluation summary for MASH test 3-11 on the single-slope barrier on slope.

Test Agency: Texas Transportation Institute

Test No.: 405160-13-1

Test Date: 2009-04-16


MASH Evaluation Criteria	Test Results	Assessment
<p><u>Structural Adequacy</u> A. <i>Test article should contain and redirect the vehicle or bring the vehicle to a controlled stop; the vehicle should not penetrate, underride, or override the installation although controlled lateral deflection of the test article is acceptable</i></p>	<p>The single-slope barrier in front of 1.5H:1V slope contained and redirected the 2270P vehicle. The vehicle did not penetrate, underride, or override the installation. Maximum dynamic deflection during the test was 5.6 inches.</p>	<p>Pass</p>
<p><u>Occupant Risk</u> D. <i>Detached elements, fragments, or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone.</i> <i>Deformations of, or intrusions into, the occupant compartment should not exceed limits set forth in Section 5.3 and Appendix E of MASH.</i> F. <i>The vehicle should remain upright during and after collision. The maximum roll and pitch angles are not to exceed 75 degrees.</i> H. <i>Longitudinal and lateral occupant impact velocities should fall below the preferred value of 9.1 m/s (30 ft/s), or at least below the maximum allowable value of 12.2 m/s (40 ft/s).</i> I. <i>Longitudinal and lateral occupant ridedown accelerations should fall below the preferred value of 15.0 Gs, or at least below the maximum allowable value of 20.49 Gs.</i></p>	<p>No detached elements, fragments, or other debris were present to penetrate or show potential to penetrate the occupant compartment, or to present undue hazard to others in the area. Maximum occupant compartment deformation was 5.5 inches. The 2270P vehicle remained upright during and after the collision event. Maximum roll was 44 degrees. Longitudinal occupant impact velocity was 12.1 ft/s, and lateral occupant impact velocity was 24.6 ft/s. Longitudinal ridedown acceleration was -2.4 G, and lateral ridedown acceleration was -11.3 G.</p>	<p>Pass Pass Pass Pass Pass</p>
<p><u>Vehicle Trajectory</u> <i>For redirective devices, the vehicle shall exit the barrier within the exit box.</i></p>	<p>The vehicle remained within the exit box.</p>	<p>Pass</p>

*Criterion K and M are preferable, not required.


REFERENCES

1. W.L. Beason, H.E. Ross, Jr., H.S. Perera, W.L. Campise, and D.L. Bullard, Jr. “*Development of a Single-slope Concrete Median Barrier.*” Texas Transportation Institute, The Texas A&M University System, College Station, Texas, 1989.
2. J.D. Michie. Recommended Procedures for the Safety Performance Evaluation of Highway Appurtenances. National Cooperative Highway Research Program Report 230, Transportation Research Board, National Research Council, Washington, D.C., March 1981
3. Ross, Jr., H.E., Sicking, D.L., Zimmer, R.A. and Michie, J.D., “Recommended Procedures for the Safety Performance Evaluation of Highway Features,” National Cooperative Highway Research Program *Report 350*, Transportation Research Board, National Research Council, Washington, D.C., 1993.
4. American Association of State Highway and Transportation Officials. *Manual for Assessing Safety Hardware*. Ballot Draft, February 2008.


A-1



PLAN



ELEVATION




END VIEW A-A

NOTE:
-SHEP 1107 PREMIUM GROUT IS USED IN BARRIER CONNECTIONS

The Texas A&M University System			
REVISIONS			
NO.	DATE	BY	CHK.
1.	2009/01/22	NDE	GG
2.	2009/01/22	NDE	NS
3.			
4.			
5.			
Project No.		Date	Drawn By
405160-13		2009/01/20	NDE
EMBEDDED BARRIERS			Scale
			Sheet No.
			1 of 5
APPROVED:			2009/01/21
NAUMAN SHEIKH:			


T:\2008-2009\405160_PooledFund\405160-13-1_SSB\405160-13-1_SSB.dwg

APPENDIX A. DETAILS OF TEST ARTICLE




DETAIL A
SINGLE SLOPE
CONCRETE BARRIER

The Texas A&M University System			
REVISIONS			
NO.	DATE	BY	CHK.
1.	2009/01/22	NDE	GG
2.			
3.			
4.			
5.			
Project No.		Date	Drawn By
405160-13		2009/01/20	NDE
EMBEDDED BARRIERS			Sheet No. 2 of 5




PLAN




ELEVATION

DETAIL A-A


The Texas A&M University System			
REVISIONS NO. DATE BY CHK. 1. 2009/01/22 NDE GG 2. 3. 4. 5.			
TEXAS TRANSPORTATION INSTITUTE COLLEGE STATION, TEXAS 77843			
Project No.		Date	Drawn By
405160-13		2009/01/20	NDE
EMBEDDED BARRIERS			Sheet No.
			3 of 5



1 1/2" NOMINAL DIA.
GALV. STEEL PIPE SLEEVE
FOR PRECAST SECTIONS
(7.5' FROM EA. END)



The Texas A&M University System					
TEXAS TRANSPORTATION INSTITUTE COLLEGE STATION, TEXAS 77843					
REVISIONS					
NO.	DATE	BY	CHK.	Project No.	Date
1.	2009/01/22	NDE	GG	405160-13	2009/01/20
2.				Drawn By	Scale
3.				NDE	
4.				EMBEDDED BARRIERS	
5.				Sheet No. 4 of 5	



DETAIL C
REBAR GRID

DETAIL D
V2 BAR (#4)

DETAIL F
V1 BAR (#4)

DETAIL E
H1 BAR (#5)

The Texas A&M University System				
REVISIONS				
NO.	DATE	BY	CHK.	TEXAS TRANSPORTATION INSTITUTE COLLEGE STATION, TEXAS 77843
1.				Project No. 405160-13
2.				Date 2009/01/20
3.				Drawn By NDE
4.				EMBEDDED BARRIERS
5.				

APPENDIX B. MATERIAL CERTIFICATION FOR TEST ARTICLE

MATERIAL USED

TEST NUMBER 405160-13-1

DATE 2009-04-16

Date received	Item number	Description	Supplier	Heat #	Quantity used
2009-03-09	CMB 1	20' single slope	Bexar Pre-cast		5
2009 01 26	REBAR8-3	1" REBAR	CMC-SHEPLERS	250430	
2009 01 26	REBAR6-5	3/4" REBAR	CMC-SHEPLERS	402-6581	

Barriers were provided by Bexar Pre-cast. No paperwork was provided.

Rebar 8-3 and Rebar 6-5 was used for connection grids in joints.

405160-13

#8



P. O. Box 911
Seguin, Texas 78156-0911
(830) 372-8200

CERTIFIED MILL TEST REPORT
For additional copies call
(830) 372-8485

We hereby certify that the test results presented here
are accurate and conform to the reported grade.

Daniel J. Schacht
Daniel J. Schacht
Quality Assurance Manager

HEAT NO.: 250430	S O L D T O	CMC HOUSTON STEEL	S H I P T O	CMC HOUSTON STEEL	SHIP#: 101796/131
SECTION: Rebar 25mmx64'0"		7077 FAIRBANKS NORTH HOUSTON		7077 FAIRBANKS NORTH HOUSTON	BOL #: 427257
Rebar 25mmx19.507		HOUSTON, TX 77040-4201		(NEW H.S.S. LOCATION)	INV #:
GRADE: ASTM A615-05a GRADE 60				HOUSTON, TX 77040-	CUST PO#:
ASTM A615M-05a GRADE 420					CUST P/N:

CHEMICAL ANALYSIS		PROPERTIES						
	%	MECHANICAL	TEST I		TEST		TEST	
			IMPERIAL	METRIC	IMPERIAL	METRIC	IMPERIAL	METRIC
C	0.39	Yield Strength	62.6 KSI	431.6 MPA				
Mn	0.81		Tensile Strength	102.9 KSI	709.5 MPA			
P	0.009	Elongation	16 %	16 %				
S	0.021		Gauge Length	8 INS	203 MM			
Si	0.18	Reduction of Area						
Cu	0.47		Bend Test	OK				
Cr	0.20	Diameter	5.00 INS	126.90 MM				
Ni	0.19		Charpy Impact					
Mo	0.056	Test Temp						
Cb	0.002		Sample Size					
V	0.000	Orientation						
Sn	0.015		Hardness					
B	0.0003							
Ti	0.001							
C.Eq.								

JOMINY RESULTS - Rockwell C hardness at 1/16th inch increments												GRAIN SIZE		INCLUSION RATING					
1	2	3	4	5	6	7	8	9	10	11	12	METHOD		METHOD					
												RESULT		TYPE					
												SIZE		SIZE					

100% MELTED AND MANUFACTURED IN THE USA AND FREE OF MERCURY CONTAMINATION IN THE PROCESS
REMARKS:

AASHTO M 31MM 31-95

B-3

APPENDIX C. CONCRETE INFORMATION

APR-28-2009 TUE 09:48 AM TERRACON

FAX NO. 9798467604

P. 02

GROUT COMPRESSIVE STRENGTH TEST REPORT

Report Number: A1071059.0013
 Service Date: 03/16/09
 Report Date: 04/13/09
 Task: PO No. 405160-13

Terracon
 6198 Imperial Loop
 College Station, TX 77845
 979-846-3767

Client

Texas Transportation Institute
 Attn: Gary Gerke
 TTI Business Office
 3135 TAMU
 College Station, TX 77843-3135

Project

Riverside Campus
 Riverside Campus
 Bryan, TX

Project Number: A1071059

Material Information

Specified Strength: 4,000 psi @ 3 days
 Mix ID: Sheplers #1107 Nonshrink Grout
 Supplier: Client
 Batch Time: 1345 Plant: Mixed on site
 Truck No.: N/A Ticket No.: N/A

Sample Information

Sample Date: 03/16/09 Sample Time: 1350
 Sampled By: Randolph E. Rohrbach
 Weather Conditions: Partly cloudy, light wind
 Accumulative Yards: Batch Size:
 Sample Size: 2 X 2 Cubes
 Sample Location: Concrete barriers on west side of runway
 Placement Location: Single slope barrier
 Form Material: Plastic Mold No. Units: 6
 Samples Plumb: Yes
 Temperature Range:

Field Test Data

Test	Result	Specification
Slump (in):		
Grout Temp. (F):		
Ambient Temp. (F):	75	

Laboratory Test Data

Set No.	Specimen ID	Measured Slump (in)	Measured Flow (sec)	Date Received	Date Tested	Age (days)	Area (sq in)	Maximum Load (lbs)	Compressive Strength (psi)
1	A	NP			03/19/09	3	4.00	20,630	5,160
1	B	NP			03/19/09	3	4.00	21,490	5,370
1	C	NP			03/19/09	3	4.00	22,920	5,730
								Average (3 days)	5,420
1	D	NP			04/13/09	28	4.00	31,800	7,950
1	E	NP			04/13/09	28	4.00	24,060	6,020
1	F	NP			04/13/09	28	4.00	29,560	7,390
								Average (28 days)	7,120

Comments: Average compressive strength of 28 day Cube complies with the specified strength. **NP = Not Performed

Samples Made By: Terracon
 Services:

Terracon Rep.: Randolph E. Rohrbach
 Reported To: Gary Gerke
 Contractor:
 Report Distribution:
 (1) Texas Transportation Institute

Started: 1300
 Finished: 1430

Lunch / Non-Chargeable:

Reviewed By:

Don H. Kopetsky
 Don H. Kopetsky
 Senior Project Manager

Test Methods: ASTM C1019

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

CR-0000

Page 1 of 1

Created: 4/14/2009
 Revised: 4/13/2009

SAMPLE PICK-UP REPORT

Report Number: A1071059.0013A
Service Date: 03/17/09
Report Date: 03/18/09
Task: PO No. 405160-13

Terracon

6198 Imperial Loop
College Station, TX 77845
979-846-3767

Client

Texas Transportation Institute
Attn: Gary Gerke
TTI Business Office
3135 TAMU
College Station, TX 77843-3135

Project

Riverside Campus
Riverside Campus
Bryan, TX

Project Number: A1071059

On March 17, 2009, a Terracon Consultants, Inc., representative was present at the above referenced project to obtain 2 sets of 3 grout cubes cast on March 16, 2009. The samples were returned to the laboratory for processing and curing.



Services:

Terracon Rep.: Mohammed Mobeen
Reported To:
Contractor:
Report Distribution:
(1) Texas Transportation Institute

Started: 1100 **Lunch / Non-Chargeable:**
Finished: 1200

Reviewed By:

Don H. Kopetsky
Don H. Kopetsky
Senior Project Manager

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written approval of Terracon. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

APPENDIX D. CRASH TEST NO. 405160-13-1

D1. VEHICLE PROPERTIES AND INFORMATION

Date: 2009-04-16 Test No.: 405160-13-1 VIN No.: 1D7HA18N82S629430
 Year: 2002 Make: Dodge Model: Ram 1500 Quad-Cab
 Tire Size: 245/70R17 Tire Inflation Pressure: 35 psi
 Tread Type: Highway Odometer: 174085

Note any damage to the vehicle prior to test: _____

- Denotes accelerometer location.



NOTES: _____

Engine Type: V-8
 Engine CID: 4.7 liter

Transmission Type:
 Auto or Manual
 FWD RWD 4WD

Optional Equipment: _____

Dummy Data:
 Type: No dummy
 Mass: _____
 Seat Position: _____



Geometry: inches

A	<u>77.00</u>	F	<u>39.00</u>	K	<u>20.50</u>	P	<u>3.00</u>	U	<u>27.50</u>
B	<u>73.25</u>	G	<u>28.12</u>	L	<u>28.75</u>	Q	<u>29.50</u>	V	<u>33.00</u>
C	<u>227.00</u>	H	<u>62.69</u>	M	<u>68.25</u>	R	<u>18.50</u>	W	<u>59.50</u>
D	<u>140.50</u>	I	<u>13.50</u>	N	<u>67.25</u>	S	<u>14.25</u>	X	<u>140.5</u>
E	<u>47.50</u>	J	<u>26.00</u>	O	<u>44.75</u>	T	<u>75.50</u>		

Wheel Center Ht Front 14.12 Wheel Well Clearance (FR) 6.12 Frame Ht (FR) 16.62
 Wheel Center Ht Rear 14.25 Wheel Well Clearance (RR) 11.25 Frame Ht (RR) 24.25

RANGE LIMIT: A=78 ±2 inches; C=237 ±13 inches; E=148 ±12 inches; F=39 ±3 inches; G = > 28 inches; H = 63 ±4 inches; O=43 ±4 inches; M+N/2=67 ±1.5 inches

GVWR Ratings:	Mass: lb	Curb	Test Inertial	Gross Static
Front <u>3650</u>	M_{front} <u>2621</u>	<u>2621</u>	<u>2743</u> Allowable	Allowable
Back <u>3900</u>	M_{rear} <u>2009</u>	<u>2009</u>	<u>2210</u> Range	Range
Total <u>6650</u>	M_{Total} <u>4630</u>	<u>4630</u>	<u>4953</u> 5000 ±110 lb	5000 ±110 lb




Mass Distribution:
 lb LF: 1368 RF: 1375 LR: 1072 RR: 1138

Figure D1. Vehicle properties for test 405160-13-1.

Table D2. Occupant compartment measurements for test 405160-13-1.

Date: 2009-04-16 Test No.: 405160-13-1 VIN No.: 1D7HA18N82S629430
 Year: 2002 Make: Dodge Model: Ram 1500 Quad-Cab

OCCUPANT COMPARTMENT DEFORMATION MEASUREMENT



	Before (inches)	After (inches)
A1	64.50	64.50
A2	64.62	64.62
A3	65.25	65.25
B1	45.56	45.56
B2	39.50	39.50
B3	45.56	45.56
B4	49.19	49.19
B5	45.56	45.56
B6	49.18	49.18
C1	29.75	29.75
C2	----	----
C3	27.56	27.56
D1	12.69	12.69
D2	2.50	2.50
D3	11.69	11.69
E1	64.44	64.25
E2	64.31	64.25
E3	64.00	63.50
E4	64.00	63.88
F	60.00	60.00
G	60.00	60.00
H	39.50	39.50
I	39.5	39.5
J*	23.62	23.62

*Lateral area across the cab from driver's side kickpanel to passenger's side kickpanel.

D2. SEQUENTIAL PHOTOGRAPHS



0.000 s



0.098 s



0.198 s



0.296 s



Figure D2. Sequential photographs for test 405160-13-1 (overhead and frontal views).



0.393 s



0.491 s



0.591 s



0.689 s



Figure D2. Sequential photographs for test 405160-13-1 (overhead and frontal views) (continued).



0.000 s



0.393 s



0.098 s



0.491 s



0.198 s



0.591 s



0.296 s



0.689 s

Figure D3. Sequential photographs for test 405160-13-1 (rear view).




Figure D4. Vehicle angular displacements for test 405160-13-1.




Figure D5. Vehicle longitudinal accelerometer trace for test 405160-13-1 (accelerometer located at center of gravity).




Figure D6. Vehicle lateral accelerometer trace for test 405160-13-1 (accelerometer located at center of gravity).




Figure D7. Vehicle vertical accelerometer trace for test 405160-13-1 (accelerometer located at center of gravity).

X Acceleration over Rear Axle




Figure D8. Vehicle longitudinal accelerometer trace for test 405160-13-1 (accelerometer located over rear axle).




Figure D9. Vehicle lateral accelerometer trace for test 405160-13-1 (accelerometer located over rear axle).

Z Acceleration over Rear Axle




Figure D10. Vehicle vertical accelerometer trace for test 405160-13-1 (accelerometer located over rear axle).